

STEP 3**TIP SHEET**

Screen ghost and haze remover

D•HAZE® Gel

Haze Remover Gel



Franmar's **D•HAZE® Haze Remover Gel** is an exclusive gel formula that allows greater control in removing ghost and haze images. **D•HAZE Gel** clings to the affected haze area and can be left on for long periods of time for stubborn ghost images. Good haze removal practices save screen printers money with longer usability of screens.

Directions:

1. Pour a small amount on screen haze/ghost image.
2. Scrub both sides of screen with a dedicated Biggee™ scrub pad or nylon brush. Set aside and leave gel to work.
3. Rinse screen clean with pressured water.

Note: Do not let D•HAZE Gel sit on adhesive holding mesh onto frames.

Usage Tips:

- Use each time immediately after emulsion or stencil removal so ghost/haze will not set in the screen.
- Great for removal of small areas of locked-in emulsion.
- An hour or longer may be necessary for older haze/ghost images, but **D•Haze Gel** will not weaken or damage mesh.
- Use Franmar's **D•GREASE™** to remove any residue.

MORE INFORMATION:

Precautions: Dispose of waste according to local regulations. Avoid eye contact. If product contacts eye, rinse thoroughly with water. Call a physician if irritation persists. If swallowed do not induce vomiting. Call a physician. Use of gloves made of butyl rubber or laminated polyethylene/EVOH is recommended.

WARNING: This product can expose you to chemicals including n-methyl-2-pyrrolidone, which is known to the state of California to cause birth defects or other reproductive harm. For more information, go to www.P65Warnings.ca.gov.



Chat with a live customer service rep:

800-538-50698:00am - 5:00pm CST Monday - Friday
or visit our website: www.franmar.com

rev. 3/30/2023