

STEP 1



TIP SHEET

Cleans screens safely and easily

UV Ink Remover



Today, industrial printers are moving to more earth-friendly inks such as UV. Franmar's **UV Ink Remover** is a superior cleaner that is low-odor, 100% biodegradable and easily degrades UV ink from screen meshes.

Directions:

1. Spray or pour a small amount onto screen.
2. Scrub screen with a dedicated Biggee™ scrub pad or nylon brush.
3. Repeat on back of screen image.
4. Clean both sides of screen with pressured water.

Usage Tips:

- Use a flip-top cap for more controlled application.
- A standard size screen generally needs only six to seven (6-7) sprays of product.
- Using Franmar's **D•GREASE™** will help with cleanup as **UV Ink Remover** will leave an oily residue.

MORE INFORMATION:

Precautions: Dispose of waste according to local regulations. Avoid eye contact. If product contacts eye, rinse thoroughly with water. Call a physician if irritation persists. If swallowed do not induce vomiting. Call a physician. Nitrile or neoprene gloves are recommended for sensitive skin.



Chat with a live customer service rep:

800-538-5069

8:00am - 5:00pm CST Monday - Friday
or visit our website: www.franmar.com

rev. 3/30/2023