STEP 4





Easy and effective screen prep

## D-GREASE"

Screen Degreaser



Franmar's **D•GREASE™ Screen Degreaser** is tough on solvent residues and easy on the environment. It is alcohol-free, non-caustic, and 100% biodegradable, making it essential for any screen printer. Its formula helps prevent "fish-eyes," and is great for prepping screens before recoating them with emulsion.

## **Directions:**

- 1. Spray or pour a generous amount onto screen.
- 2. Scrub screen with dedicated Biggee™ scrub pad or nylon brush.
- 3. Make sure to scrub near edge of frame to remove all contaminants.
- 4. Rinse both sides of screen thoroughly with water.

## **Usage Tips:**

- Remember: The cleaner the screen, the better the emulsion adheres to the mesh.
- D•GREASE™ works well for removing leftover cleaning residue.
- Helps prevent pinholes from dirt and debris.

## **MORE INFORMATION:**

**Precautions:** Dispose of waste according to local regulations. Avoid eye contact. If product contacts eye, rinse thoroughly with water. Call a physician if irritation persists. If swallowed do not induce vomiting. Call a physician. Nitrile or neoprene gloves are recommended for sensitive skin.



Chat with a live customer service rep:

800-538-5069

8:00am - 5:00pm CST Monday - Friday or visit our website: www.franmar.com